
P 0 6/82	P1 687	INVENT	ORY	Pacific No	tional Park Service cific Northwest Region tural Resources Division				1 Sixt	er.	1920 on 98121	
2 NAME(S) OF STRUCTURE		5. ORIGINAL USE	7. CLASS	IFICATION						T	3	9. RATING
Tipsoo Lake Con	nfort Station	Comfort Station									1,	O, DATE
3 SITE ADDRESS (STREET & NO)		6. PRESENT USE										1933-34
Tipsoo Lake 0-0	060	Same	8. UTM	ONE EAST	ING		NORTH	ING			Ţ,	1. REGION
4. CITY/VICINITY	COUNTY	STATE	SCALE	1:24	1:62 5			QUAI				
Chinook Pass 12 OWNER/ADMIN ADDRESS	Pierce	Washington	<u> </u>	OTHER				NAMI	E			
Log and masonry tongue anasonry tongue anasonry tone masonry ment windows; concrete slab	ier National Park, Tahoma V UND HISTORY INCLUDING CONSTRUCTION DATE(S), I TECTS, ENGINEERS, ETC y frame, one story, two roc DOVE sheathing and log rafte walls lower half, log post concrete foundation; expose floor. y up to Cayuse Pass, then e	on the second of	ure; mx; proje quarter seams	edium pitc ecting eav clog vene 1 x 4 to	thed ced wes and eer at g ongue ar	verg gable nd gr	es;] ends oove	log i s; h inte	ridge orizo erior	e bea ontal wal	am; L cas Lls;	se-
was opened to the NPS Branch development of never complete were construct	traffic in 1932, providing of Design and Plans, under tourist facilities at Tips ly carried out. Only the ed (Thompson 1981: 163). Tipsoo Lake comfort statics strucred at Yakima Park (Su	a new entrance into to the supervision of Cooo and Chinook Pass. entrance arch and a date on the remains intact. B	he parl hief An Howeve y use a uilt by	c. Superi chitect T er, Tomlin area at Ti the CCC	ntender C.C. Vir nson's a psoo La in 1933	nt To nt, t embit ake w 3-34,	mling to predictions with the	son (epare des: two (thus e pla igns comfo	requans for the second	ueste For t e stati	ed the ions lar
14 CONDITION	EXCELLENT GOOD SFA	A DETERIORATED	RUINS	15, DAN	IGER OF DEMO	DLITION?	□ YE	ES	□no	⊠ ¹	UNKNOW	vn


KYSKHADEKKK

station. Condition of the building is good except for a missing log beam-purlin on side facade that supports eave-roof slope. A log post has been inserted at one gable-verge end to provide roof support.

17 PHOTOS AND SKETCH MAP OF LOCATION







18. LOCATED IN AN HISTORIC DISTRICT?	☐YES	©3NO	DNAME								
19 PUBLIC ACCESSIBILITY YES, LIM	IITEO [XYES, UNLIM	TED	20. EXISTING SURVEYS	□ NR	ITY DLOC	HABS	□HAER-1]OTHER	HAER	MPS	STATE

21 REFERENCES-HISTORICAL REFERENCES, PERSONAL CONTACTS, AND/OR OTHER

Building File O-060, Maintenance Division, Mt. Rainier National Park. Prepared by Drysdale, Report on Construction, 1933; K.L. Smith, building data, 1933; photo, no date.

Erwin N. Thompson, Mount Rainier National Park, Washington: Historic Resource Study (Denver: Historic Preservation Branch, Denver Service Center, National Park Service, 1981).

David Harvey

0